Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
S1	1111 ·	361/23.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/03 12:13
S2	372	361/33.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/05 16:10
S3	35262	motor same relay same voltage	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/03 12:54
S4 .	7339	S3 same (coil magnet) same (armature rotor)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/03 12:34
S5	25	S4 and S2	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/03 12:18
S6	10377	S3 and (coil magnet) same (armature rotor)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/03 12:35
S7	34	S6 and S2	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR .	ON	2006/07/03 12:35
S8	9	S7 not S5	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/03 12:35
S9	623	S3 same (first adj relay) same (second adj relay)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/03 12:55
S10	110	S9 same delay	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/03 12:55
S11	53	S10 and (user operator joystick (touch adj panel) button)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/03 12:56

Co.		(1000555501 100707 1011 10010501 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 1011 101	1	-	1	0000:
S12	6	("0965059" "3727118" "3818291").PN. OR ("4406979"). URPN.	US-PGPUB; USPAT; USOCR	OR	ON	2006/07/03 14:02
S13	82	S2 and ((low adj voltage) undervoltage)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/03 14:33
S14	98	S1 and ((low adj voltage) undervoltage)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/03 14:33
S15	95	S14 not S13	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/03 14:38
S16	574	(undervoltage (low adj voltage)) adj protection	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/03 14:39
S17	124	S16 same motor	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/03 14:39
S19	7	S17.ti.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/03 14:45
S20	54	(motor and relay and power and delay and frequency).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/03 14:46
S21	1563	motor same relay same stick	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/05 10:26
S22	601	S21 same power	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/05 10:27
S23	2	S22 and (S1 or S2)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/05 10:27

S24	2042	motor same relay same stick\$5	US-PGPUB;	OR	ON	2006/07/05 10:43
		,	USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB			2503/51/65 16/45
S25	805	S24 same power	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/05 10:27
S26	1111	361/23.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/05 10:27
S27	372	361/33.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/05 10:27
S28	4	S25 and (S26 or S27)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/05 10:27
S29	1563	motor same relay same stick	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/05 10:27
S30	601	S29 same power	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/05 10:27
S31	2	S30 and (S26 or S27)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/05 10:27
S32	2	S28 not S31	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/05 10:27
S33	1800	power same relay same stick\$5	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/05 10:43
S34	318	power with relay with stick\$5	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/05 10:49

S35	12	S34 same (first adj (contact relay)) same (second adj (contact relay))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/05 10:50
S36	42	S33 same (first adj (contact relay)) same (second adj (contact relay))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/05 10:45
S37	776	power with (contact relay) with stick\$5	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/05 10:50
S38	16	S37 same (first adj (contact relay)) same (second adj (contact relay))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/05 10:50
S39	7	("1809827" "3413535" "3711747" "4060841").PN. OR ("4151575").URPN.	US-PGPUB; USPAT; USOCR	OR	ON	2006/07/05 14:51
S40	28784	motor same relay same (reversibl\$1 revers\$3 bidirectional (bi adj directional))	US-PGPUB; USPAT; USOCR	OR	ON	2006/07/05 14:52
S41	22418	S40 same contact\$3	US-PGPUB; USPAT; USOCR	OR	ON	2006/07/05 14:52
S42	1316	S41 same (weld\$3 stick\$5 stuck)	US-PGPUB; USPAT; USOCR	OR	ON	2006/07/05 14:57
S43	10	(("3671834") or ("4756494") or ("3914675") or ("4077753")).PN.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/07/05 14:58
S44	10	(("3671834") or ("4756494") or ("3914675") or ("4477753")).PN.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/07/05 14:58
S45	9	("2437197" "2606312" "3046462" "3284648").PN. OR ("3671834").URPN.	US-PGPUB; USPAT; USOCR	OR	ON	2006/07/05 15:26
S46	372	361/33.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/05 16:10
S47	5	S46 and ((stick\$3 weld\$3) same (relay contact))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/05 16:18

					,	
S48	1111	361/23.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/05 16:18
S49	41	S48 and ((stick\$3 weld\$3) same (relay contact))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/05 17:21
S50	41	S49 not S47	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/05 16:19
S51	4386	motor same relay same (reversible reverse bi-directional)	USPAT	OR	ON	2006/07/05 16:48
S52	2526	S51 same contact\$	USPAT	OR	ON	2006/07/05 16:48
S53	21	S52 same (welded stick\$5)	USPAT	OR	ON	2006/07/05 16:48
S55	18	S49 and delay	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/05 17:31
S56	554	motor same relay same reclose same delay	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/05 17:29
S57	21	S56 same (weld\$3 stick\$3)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/05 17:26
S58	701	motor same reclose same delay	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/05 17:27
S59	30	S58 same (weld\$3 stick\$3)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR .	ON	2006/07/05 17:26
S60	67	S58 same fault	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/05 17:27
S61	6956	delay same frequency same relay	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/05 17:28

					т	
S62	252	S61 same (weld\$3 stick\$3)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/05 17:28
S63	142	S62 same (reclose close on)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/05 17:28
S64	2189	relay same (weld\$3 stick\$3) same delay	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/05 17:29
S65	4768	motor same relay same (weld\$3 stick\$3)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/05 17:30
S66	6	S65 and (reclose with delay)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/05 17:30
S67	12	S53 and delay	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/05 17:35
S68	478	relay with reclos\$3 with delay	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/05 17:35
S69	10	S68 and motor.ab.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/05 17:35
S70	62	motor same relay same ((reapply\$3 reapplication) adj2 power)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/06 09:16
S71	42	S70 same (time delay)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/06 09:17

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L4	4515	(car vehicle) same (chair seat) same (position\$3) same motor same (button switch)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/06 13:48
L5	35609	(car vehicle) with (chair seat) with (position\$3)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/06 13:48
L6	1843	5 with (button switch\$3)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/06 13:48
L7	444	6 with motor	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/06 13:48
L8	65	7 with (operator user)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/06 14:09
L9	974	thermoswitch	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/06 14:10
L10	244	9 same motor	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/06 14:10
L11	11	10 same armature	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/06 14:17
L12	12	10 same rotor	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/07/06 14:17